

## 2019 Museum and Gallery Building Improvement Program - Recipients

| Recipient                   | Project Name        | Summary   | Amount Awarded |
|-----------------------------|---------------------|---|----------------|
| Armidale Folk Museum        | Building Works      | To install UV filter film and block out blinds on the windows and skylights to prevent light damage to objects.   | \$8,387        |
| Nowra Museum                | Building Works      | The removal of the rear concrete platform in order to eliminate the sporadic flooding of the entrance/meeting room and the Exercise Yard archival storage area and reduce moisture levels.  | \$15,000       |
| NSW Lancers Memorial Museum | Building Works      | To replace window glazing putty replacement and window painting, install roof and ceiling insulation to level 1 of Linden House and clear space in the Annexe and purchase more metal shelving  | \$3,173        |
| Bank Art Museum Moree       | Building Assessment | To engage a consultant to identify and report on building improvement needs, including but not limited to, reviewing areas of wall and ceiling breaches in the main building and workshop's fabric and reviewing secondary internal staircase for structural integrity in case of emergency | n/a            |
| Bellingen Museum            | Building Assessment | To engage a consultant to identify and report on building improvement needs, including but not limited to, door sealings, pest access points, temperature and humidity fluctuation and object storage areas.  | n/a            |
| Narrandera Parkside Museum  | Building Assessment | To engage a consultant to identify and report on building improvement needs to provide the Committee and Council with guidance as to most urgent works required, allowing the committee to prioritise and focus energy on securing resources to address the most urgent issues.             | n/a            |
| Scone Museum                | Building Assessment | To engage a consultant to identify and report on building improvement needs, including but not limited to, cracks in walls, gaps in cornices and walls, water leak damaged ceiling and examine areas of weathering on   | n/a            |

|                |                     |  |     |
|----------------|---------------------|--|-----|
| Wingham Museum | Building Assessment | To engage a consultant to identify and report on building improvement needs, including but not limited to, integrity and suitability of the entry to the museum, integrity and suitability of the “Wingham Town” building and compliance with relevant building regulations. | n/a |
|----------------|---------------------|--|-----|